


INCORRECT

POSITIONING OF CONTAINERS ON VEHICLES




ie. Containers are not Flush with the Rear of the Trailers

RIGID TRUCK




REMARKS


SKELETAL SEMI-TRAILER



RIGID - TRAILER COMBINATION



INTER LINK



DDL Equipment Pty Ltd

Reg No: 2005/043409/07


E-Mail: sales@ddl.co.za

Website: www.ddl.co.za

Tel: 011 393 1209

Fax: 011 393 1169

6 Neutron Road, Chloorkop, Kempton Park



Ref: DE.30HIP